

## State of New Hampshire DEPARTMENT OF ENVIRONMENTAL SERVICES

6 Hazen Drive, P.O. Box 95, Concord, NH 03302-0095 (603) 271-3501 FAX (603) 271-6683



ER OF DE ICIENCY

No. WD SS 03-02

March 20 2

Mr. Thomas Foote PO Box 159 Marlow, NH 03456

RE Marlow Property

Dear Mr Foote

On March 10, 2003 personnel from the Department of Environmental Services, Water Division ("DES") received information from the Town of Marlow concerning your property, described as Lot #65, on Tax Map #405, and located on Marlow Hill Road, Marlow, NH, 03456 ("the Property"). The purpose of the Town's inspection was to determine whether you were in compliance with RSA 485-A and it's implementing regulations, the Subdivision and Individual Sewage Disposal System Design Rules, Env-Ws 1000 ("the Rules").

As a result of the inspection the following deficienc was noted

1. The Property has running water but does not have an approved septic waste disposal system installed. The waste product is running out of a straight pipe onto the ground on the Property.

DES expects the above deficiency to be permanently corrected within 30 days by initiating and completing the following measures:

Engage a permitted septic system designer to prepare and submit septic system plans and specifications to DES for the total waste load generated on the Property.

Obta approval construct the system

Const act and ob in approval to cover and ase the system

perate and maintain the syste ac rdance with N

Adm strative Rule Env-Ws 102

During interim between receipt of this letter and the date by which permanent corrections have been completed, as an alternate to vacating the premises, DES expects that collected sewage will be pumped and

http://www.state.nh.us TDD Access: Relay NH ·800-735-2964

WD SS 03-02 Foote Page 2

disposed in accordance with NH Administrative Rule Env-Ws 800 at sufficient frequent intervals to prevent further overflow. If this alternative is utilized, it is advised that pumping receipts be retained.

DES believes the cited deficiencies will be corrected within 30 days and a report describing the corrective measures can be submitted to this office within 45 days of receipt of this letter.

In the event compliance is not achieved within this period, DES may take further action against you, including issuing an order requiring the above items to be corrected, initiating an administrative fine proceeding, and/or referring the matter to the New Hampshire Department of Justice for imposition of civil and/or criminal penalties. In addition, DES personnel will inspect the Property at a later date to determine whether you have come into, and are maintaining, full compliance with all applicable statutes and directives.

The written report as requested above should be addressed as follows:

Richard J. de Seve, SSB, DES Department of Environmental Services 6 Hazen Drive, PO Box 95 Concord, NH 03302-0095

Your prompt cooperation is appreciated. Should you have any questions regarding this letter, please contact Richard J. de Seve at 271-3442.

Sincerely,

William E. Evans, P.E.

Administrator

Subsurface Systems Bureau

WEE/RJD

CERTIFIED MAIL 7099 3400 0003 0696 2293

Cc: James G. Falicon, SSB, DES
Gretchen C. Rule, Enforcement Coordinator, DES
Russell A. Nylander, Chief Engineer, WD
Board of Selectmen, Town of Marlow
Richard J. de Seve, SSB, DES